

BLISS
EUROPE

THE
SPiRiT[™]
TO WALK AN EXTRA
MILE

Safety Features on Indicators Safety First





Float failure Indication Standard

The bottom three flags on the Indicating Assembly are set in reverse color to provide a visual indication in case the Float fails and lodged at the bottom of the Chamber, while in operation.

This way you know when to 'Turn off' your isolation valves and call us for a replacement of Float.




Unique Features

Wide Track Indicator

- Our new Wide Track design ensures visible indication at 200 ft. away from the tank.
- All metal flags make it suitable for On-shore as well as Off-shore applications.
- Interlocking mechanism restricts movement of flags to 180°
- Hermetically Sealed indicators
- For Offshore applications:
 - Flag assembly - Stainless Steel
 - Indicator enclosure - Stainless Steel



Further, we can provide custom colors as per your preference.



18-129/L3-Safety



Bliss Europe

Maidstone 48, 5026 SK, Tilburg, The Netherlands
Tel.: +31 (0) 13 304 0111, Fax.: +31 (0) 13 533 9688
Email: sales@blisseurope.eu, info@blisseurope.eu

www.blisseurope.eu

GLOBAL
PRESENCE

USA | CANADA | EUROPE | SOUTH AMERICA | MIDDLE EAST | SAUDI ARABIA | ASIA